


This lead.


So used it to run a lead to the light bulbs wired in



~~parallel~~

parallel. I checked at each stage that there was power to the connectors. All connectors properly crimped with wire tinned first with soldering iron

earthing point found where dashboard attaches to bracket



So all put back together & radio still works, and the dashboard lights too! Have not checked to see if the thermostat works.

13/4/14